23	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	∞	7	6	5	4	w	2	ш			
<u>'~</u>	_	0		-	7 VB151	5 VB148	VB126	1 VB103	,				RayMS2	3	7 RAY231	5 R003		+	3	P002						ELD123	E001		Eld001	Elden1		,		
					51	48	26	03			Rey Rm 114a RT		MS2		231 ·	3	Ray MS1			2	Palm001A	Palm001				123	1	Eld001A)01	n1	Sample No.			Α
					VanBuren	VanBuren	VanBuren	VanBuren		TK	Reynolds ES		Ray MS		Ray MS	Ray MS	Ray MS			Palmer ES	Palmer ES	Palmer ES		Elden ES		Elden ES	Elden ES	Eiden ES	Elden ES	Elden ES	Building			В
					1st flush	1st flush	1st flush	1st flush		30sec draw	1st flush		1st flush		1st flush	1st flush	1st flush			1st flush	30sec draw	1st flush				1st draw	1st draw	30sec flush	1st draw	1st draw	Flush/30sec draw	Description (First		С
	CF - Classroom Faucet	DF - Drinking Fountain			1/13/2017	1/13/2017	1/13/2017	1/13/2017		4/6/2016	4/6/2016		6/9/2016	,	1/13/2017	10/20/2016	6/9/2016			10/20/2106	8/26/2016	8/26/2016				1/13/2017	10/20/2016	8/26/2016	8/26/2016	6/9/2016	Date			D
		Fountain			7:06	7:04	7:03	7:01		6:46	6:45		6:18am		6:26am	8:02am	6:11am			7:29am	9:02am	9:01am				6:44am	7:16am	9:19am	9:18am	6:34am	Time Sampled			E s
					Rm 151	Rm 148	Rm 126	Rm 103		Rm 114	Rm114		Rm 139a		Room 231	Room 231	Room 231			Kitchen	Kitchen	Kitchen		Hall nr. 126		Hall nr 123	Hall nr 123	Hall nr 123	Hall nr. 123	Hall nr. 123	Water Outlet	Location of		F
					유	유	유	유		DF	DF		CF		무	PF	₽F	1	,	spigot	Spigot	spigot		DF		DF	DF	무	무	DF	sink, DF)	Outlet (i.e.	* Type of	G
					1st retest	1st retest	1st retest	1st retest		=	1st retest		II .		3rd retest	2nd retest	1st retest			2nd Retest	7	1st retest				4th retest	3rd retest	=	2nd retest	1st Retest	Notes			Ŧ
					ω	22	14	17		2.7	9.9		12		9	21	17			2	1 12	17				12	59	14	140	49	(ppb)	Conc.	Lead	-
				14	Below limits-	Above limits- will have to correct	Below limits	Above limits- will have to correct		Location below limits - Back in service	Location below limits - Back in service		Location below limits - Back in service		Location below limits - Back in service	Above limits - will have to correct	Above limits - will have to correct			Location below limits - Back in service		Above limits - will have to correct		Pernamently Removed from service		Location below limits - back in service	Above limits - will have to correct		Above limits - will have to correct	Above limits - will have to correct	Comments			
				8	Replaced fauct aerator	Replaced fauct aerator	Replaced fauct aerator	Replaced fauct aerator			Replaced faucet & supply piping		Replaced sink faucet		Ran new supply pipe from main connection	Replaced supply valve & fittings	Placed drinking foutain with new unit			Longer flush		Replaced pot/kettle filler faucet				Ran new supply pipe from main connection	Replaced supply pipping		Replaced brass fittings	Replaced bubbler & Valve	Remediation action taken			~